



### Suggested method of wrapping the Casket


1. Place one sheet of Shrinkable polyethylene film "sheet"



2. Place casket on sheet.




3. Fold up short side of sheet.



*Fig. 1 sheet 1*

4. Bring sheet over the casket




5. Suggestion for folding ends.

1. Fold in sides

2. Fold bottom up

3. Fold top down

4. Finished fold



6. Apply heat. Keep heat gun moving at all times. Start at one end and continue around casket. Press wrap together with gloved hand to seal all seams. A perfect seal is not required in this step. It is also not necessary to remove all wrinkles as the wrap tightens as it cools.

7. Suggestion for sealing seams. Put on one piece along the long seam. Place two pieces on each end using an X pattern. Make sure all seams are sealed. If a hole should develop during the heating process just patch it with tape. It is not necessary or advisable to heat tape.

8. Apply filter. Cut hole to match size of hole in filter. The filter should be placed on a smooth clean surface towards the top of the casket. Press firmly.

Fig. 1 sheet 2